

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program November 4, 2008

Reviewed:

Mine Name: Black Butte

Operator Name: GoldTerra

2008 **Time:** About 4:30-6:00 PM

Inspector(s): Paul Baker Other Participants: None Mine Status: Inactive

Weather: Mostly clear, 60s

Permit number: S0150080

Inspection Date: October 16,

Elements of Inspection 1. Permits, Revisions, Transfer, Bonds, Permit Fees 2. Public Safety (shafts, adits, trash, signs, highwalls) 3. Protection of Drainages / Erosion Control 4. Deleterious Material 5. Roads (maintenance, surfacing, dust control, safety) 6. Concurrent Reclamation 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) 8. Soils 9. Revegetation 10. Other Evaluated Comment Enforcement Enforcement Comment Enforcement Enforcement Comment Enforcement

Purpose of Inspection:

Brett Gregory, an intern working for the Division, inspected this site on July 28, 2008, and noticed several trenches. I wanted to verify this information and map the trenches to see how much land had been disturbed and where these trenches were in relation to the permitted mine disturbance and to section lines.

Inspection Summary:

1. Permits, Revisions, Transfer, Bonds, Permit Fees

On November 16, 2007, the Division approved an update to the reclamation plan which changed the disturbed area acreage from five acres to one acre. The Division holds a reclamation surety of \$5400.00 which is adequate for one acre.

7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)
The attached map shows the trenches I was able to map. After taking data for these trenches, the satellite configuration changed enough that I was no longer able to collect points, so I did not complete the mapping. There were about three trenches in addition to the 16 shown on the map.

The trenches were mostly about 20 feet wide, but one averaged about 40 feet. The actual widths varied, and these figures underestimate the actual disturbance areas. The trenches were mostly about 3-4 feet deep with deeper and shallower places. A pile of material had been pushed up at the end of each trench with some piles on the sides as well.

Inspection Date: October 16, 2008, 2008; Report Date: November 4, 2008

Page 2 of 3 Permit Number

Disturbance from the trenches shown on the map was conservatively estimated at 1.96 acres. I paced the length of three additional trenches, and they add about 0.22 acres for a total of 2.18 acres. The access road is estimated to be 0.17 acres bringing this total, not including the mine itself, to 2.35 acres. I have not tried to estimate the size of the mine itself.

Conclusions and Recommendations:

The mine and the road should be no larger than one acre, and this is probably about right. Therefore, the total disturbance, including the trenches, the road, and the mine, is approximately three acres.

None of the disturbance associated with the trenches was permitted. The mine is supposed to be entirely within Section 2 of Township 20 South, Range 14 East, SLM, but the disturbance extends on to BLM land in Section 1.

I had planned to take enforcement action, but the operator's representative, Dan Sheppard, informed by voice and e mail on November 25, 2008, that the trenches have been regraded. The operator needs to seed the disturbed areas, and the Division and operator will need to monitor them for revegetation success. There is not a lot of vegetation in the area, but there is some. I recommended to the operator a seed mix that includes mat saltbush, Castle Valley clover, and Indian ricegrass.

Inspector's Signature

PBB

cc: Dan Sheppard, GoldTerra Will Stokes, SITLA Chris Conrad, Price BLM

O:\M015-Emery\S0150080-BlackButte\inspections\ins-10162008.doc



Photo 1. This and Photo 2 show two of the trenches.



Photo 2.

Inspection Date: October 16, 2008; Report Date: November 4, 2008

Page 3 of 3 S0150080




Photo 3. The piles across the center of this photo are associated with trenches.





Photo 4. One of the trenches is near the foreground, and the piles in the center-left of the photo are connected with other trenches.



Township 20 S Range 14 E Section 02 SLBM Mine Number: S0150080 Mine Name: Black Butte

Inspection Date June 30, 2004 Map Produced by DKS

2.13 0 0


2.13


00

00

Township or range Line or range line: location doubtful


SITLA Mineral Ownership SITLA Mineral Leases CommunityPit Preinw 8LMSulabinMinerals






625

Different data sources and input scales may cause misalignment of data layers. This product may not meet DOGM standards for accuracy and content





ownship 20 S Range 14 E Section 02 SLBM Mine Name: Black Butte Mine Number: S0150080

Inspection Date June 30, 2004 Map Produced by DKS 0 0 0 0

Total Acres Distrubed 2.13


Acres Excluded
Acres PreExisting Acres Released 0000


Acres Prelaw

Legend
All items symbolized in legend may not be appear on map


Township or mage Line --- Township or range line: location doubtful SiTLA Mineral Lesses Presaw BLMSalableMinerals mmunityPit

SITLA Mineral Ownership






Different data sources and input scales may cause misalignment of data layers. This product may not meet DOGM standards for accuracy and content.



Mine Name: Black Butte Mine Number: S0150080

Township 20 S Range 14 E Section 02 SLBM



Different data sources and input scales may cause misalignment of data layers. This product may not meet DOGM standards for accuracy and content.

Verify Scale